




# SOLDERING

KEEP IT SAFE

TAKE PROPER SAFETY PRECAUTIONS WITH OPERATING EQUIPMENT



## Protection

- Before getting started make sure to put on safety glasses. This will avoid any solder splatter or other materials falling into eyes.
- At the end of any soldering projects make sure to wash your hands thoroughly.



## Caution Hot

- Soldering iron is incredibly hot!
- Soldering iron temperature can reach up to 650°F-900°F
- Keep hands away from tip of soldering iron.
- Only hold the soldering iron by the rubber grip.



## Exhaust

- Solder emits smoke when heated
- This smoke is a combination of solid particles and gases that can be harmful if inhaled.
- Ensure to turn on and have exhaust close to work area to draw away and filter smoke.