


Mitre cutting of Blindspace boxes

Profiles are viewed as shown, with the short side facing you
X = cut size, which is the long side excluding the flange


OPTION 1

LH mitre, cover hinge on long side




OPTION 2

RH mitre, cover hinge on long side




OPTION 3

LH mitre, cover hinge on short side




OPTION 4

RH mitre, cover hinge on short side



NB: If ordering profile with one flange, you MUST specify whether the flange is on the long side or the short side



Angles are measured from a perpendicular cut, as shown (diagram viewed from above).